

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

| | | | |
|------------------|--------------------------------|---|------------------------|
| In re: | Jean-Paul ALBERT |) | |
| Patent No.: | 6,913,310 |) | Confirmation No.: 6425 |
| Issued: | July 5, 2005 |) | |
| Group Art Unit: | 3612 |) | |
| Examiner: | Kiran B. Patel |) | |
| Attorney Docket: | 8953-95214 |) | |
| Customer No.: | 42798 |) | |
| Title: | GLASS ROOF FOR A MOTOR VEHICLE |) | |

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT

Commissioner for Patents
Office of Patent Publication
ATTN: Certificate of Correction Branch
P.O. Box 1450
Alexandria, Virginia 22313-1450

Dear Sir:

It is requested that a Certificate of Correction be issued to correct errors found in the above-identified patent. Attached hereto is a Certificate of Correction, in duplicate, which indicates the following requested corrections:


In the drawings, Sheet 3, FIG. 5, the reference numeral 8a should be applied to the same projecting part as the reference numeral 8b is applied to, and the reference numerals 6a, 6b should be applied to the element from which the projecting parts (8a, 8b) project from.

The certificate of correction fee in the amount of \$100 is being paid electronically via Deposit Account No. 06-1135.

Applicant hereby petitions for the Commissioner to charge any additional fees or any underpayment of fees which may be required for this Response, and which may be required to maintain the pendency of this case at any time during prosecution, or to credit any overpayments to Deposit Account. 06-1135.

Respectfully submitted,

Date: January 4, 2010



John M. Naber
Registration No. 46,487

FITCH, EVEN, TABIN & FLANNERY
1120 20th Street, NW; Suite 750-S
Washington, D.C. 20036
(202) 419-7000 Main
(202) 419-7012 Direct
(202) 419-7007 Fax
jnaber@fitcheven.com

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page 1 of 1

PATENT NO. : 6,913,310

APPLICATION NO.: 10/601,192

ISSUE DATE : July 5, 2005

INVENTOR(S) : Jean-Paul Albert

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

In the Drawings, Sheet 3, Figure 5:

The reference numeral 8a should be applied to the same projecting part as the reference numeral 8b is applied to, and the reference numerals 6a, 6b should be applied to the element from which the projecting parts (8a, 8b) project from.

MAILING ADDRESS OF SENDER (Please do not use customer number below):

John M. Naber
Fitch, Even, Tabin & Flannery
1120 20th Street, NW; Suite 750-S
Washington, D.C. 20036

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process) an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Time will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggestions for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: **Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.**

If you need assistance in completing the form, call 1-800-PTO-9199 and select option 2.